

Attachment 2 – Photographs of site and surrounding area

Subject Site



Project description: Subject site, front façade of primary structure.



Photograph description: Subject site, side yard, northerly.



Project description: Subject site, front façade – windows.



Project description: Subject site, front façade, large picture windows.



Project description: Chimney (brick material) on southerly side of dwelling.



Project description: Chimney (stucco) on northerly side of dwelling.



Project description: Subject property, southerly side, large picture window.



Project description: Subject site, rear yard, garage structure.



Project description: Subject site, rear yard, garage structure.



Project description: Subject site, rear yard, garage structure.

Adjacent Properties







Project description: Neighboring property, across Westwood Place.



Project description: Neighboring property, across Westwood Place.

Surrounding Neighborhood



Photograph description: 1726 Westwood Pl, Minimal Traditional style. Mirrors 1723 Westwood Pl in façade and layout, one exception is the attached garage instead of a large picture windows.



Photograph description: 1740 Westwood Place, 1993 Citywide Survey identified as Minimal Traditional, construction date: 1940.



Photograph description: 1741 Westwood Place, 1993 Citywide Survey identified as Minimal Traditional, construction date: 1942.



Photograph description: 1765 Westwood Place, 1993 Citywide Survey identified as Minimal Traditional, construction date: 1942.



Photograph description: 1794 Westwood Place, 1993 Citywide Survey identified as Minimal Traditional, construction date: 1941.



Photograph description: 1808 Westwood Place, 1993 Citywide Survey identified as Minimal Traditional, construction date: 1941.



Photograph description: 1840 Westwood Place, 1993 Citywide Survey identified as Minimal Traditional, construction date: 1941.



Photograph description: 1870 Westwood Place, 1993 Citywide Survey identified as Minimal Traditional, construction date: 1939.



Photograph description: 1882 Westwood Place, 1993 Citywide Survey identified as Minimal Traditional, construction date: 1940.



Photograph description: 1890 Westwood Place, 1993 Citywide Survey identified as Minimal Traditional, construction date: 1940.



Photograph description: 1890 Westwood Place, 1993 Citywide Survey identified as Minimal Traditional, construction date: 1940.



Photograph description: 1960 Westwood Place, 1993 Citywide Survey identified as Minimal Traditional, construction date: 1942.



Photograph description: 1977 Westwood Place, 1993 Citywide Survey identified as English Tudor Revival, construction date: 1942.



Photograph description: 1961 Westwood Place, 1993 Citywide Survey identified as Colonial Revival, construction date: 1940.



Photograph description: 1925 Westwood Place, 1993 Citywide Survey identified as Minimal Traditional, construction date: 1939.