

State of California - The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary #
HRI #
Trinomial
NRHP Status Code

Other Listings
Review Code

Reviewer

Date

Page 38 of 277

*Resource Name or #: (Assigned by Recorder) 1515 GANESHA

P1. Other Identifier:

*P2. Location: ☐ Not for Publication

and (P2b and P2c or P2d. Attach a location map as necessary.)

*b. USGS 7.5' Quad _____ Date _____ T _____; R _____; 1/4 of _____ 1/4 of Sec _____; B.M.

c. Address 1515 GANESHA City: Riverside Zip _____

d. UTM (Give more than one for large and/or linear resource Zone _____; mE/ _____ mN _____)

e. Other Locational Data: Contributing

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This Minimal Traditional is a rectangular form with two front cross-gables. There are two original bump-out bay windows and one center picture window. Windows are single-paned double-hung. Front porch is simple covered entryway with iron supports. Front door and iron door knocker are original. Wall cladding is smooth stucco. Garage is detached, with modern roll-up door.

*P3b. Resource Attributes: (List attributes and codes)

*P4. Resources Present: ☐ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other (isolates, etc.)

P5b. Description of Photo:
(View, date, accession #)

*P6. Date Constructed: 1947

Age and Sources: ☒ Historic

☐ Prehistoric ☐ Both

*P7. Owner and Address:

Riverside CA

*P8. Recorded by: (name, affiliation, and address)

*P9. Date Recorded:

*P10. Survey Type: (Describe)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.")

*Attachments: NONE ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record
☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record
☐ Artifact Record ☐ Photograph Record Other (List) _____

1515 Ganesha Pl



