

Response: 2018-0251216-000

Incident	0251216-000
Incident Date	08/19/2018
Incident Status	Closed
Alarm Time	08/19/2018 05:57:38
Arrival Time	08/19/2018 06:02:59
Controlled Time	08/19/2018 00:00:00
Cleared Time	08/19/2018 10:57:16
Incident Type	111 - Building fire
Shift	C
Station	185
Alarms	1
Mutual Aid	N - None
Actions Taken 1	11 - Extinguish
Actions Taken 2	12 - Salvage & overhaul
Actions Taken 3	80 - Information, investigation & enforcement, other
Officer In Charge Date	08/21/2018

Location: 2018-0251216-000

Location Type	1 - Street Address
Directions	btwn S THOMAS ST
Address	248 W GRAND Ave
City	POMONA
State	CA
Census Tract	402502
Longitude	117.75139
Latitude	034.04777
Property Use	419 - 1 or 2 family dwelling
Estimated Property Loss	300,000.00
Estimated Content Loss	50,000.00
Est. PreIncident Property Value	327,000.00
Est. PreIncident Content Value	50,000.00

Resources: 2018-0251216-000

Unit LF185

Main Use 3 - Other
Unit Type 12 - Truck or aerial
Dispatch Time 08/19/2018 05:57:38
Enroute Time 08/19/2018 05:58:25
Arrival Time 08/19/2018 06:02:59
Clear Time 08/19/2018 10:56:42
Reporting Member 242707 ROY JAMES E
Assignment Date 08/19/2018

Narrative Unit Narrative
At 0557 hours on Sunday, August 19, 2018 Unit LF185 was dispatched to a building fire. Seven personnel responded. We arrived on scene at 0602 hours and cleared at 1056 hours.
COA - SFD WELL INVOLVED WITH SMOKE/FIRE, OCCUPANTS OUTSIDE, LIVE ELECTRICAL WIRE DOWN IN STREET
ACTION TAKEN: OFFENSIVE ATTACK, TRANSITIONAL EXTERIOR TO INTERIOR ALONG WITH VERTICAL VENTILATION.
E182 COMMAND, INITIATED FIRE ATTACK (EXTERIOR), ASSIGNED RESOURCES
E183 FIRE ATTACK
E184 EXPOSURES, ASSIST F.A., UTILITIES
E188 MANPOWER
E121 RIC, ASSISTED WITH MEDICAL
S184 MEDICAL GROUP
BN.19 I.C.
LF185 VENTILATION, FORCIBLE ENTRY, ASSIST IN F.A..
CAUSE UNDER INVESTIGATION BY INVESTIGATORS 1,3,9.
RED CROSS, EDISON, GAS CO. AS ASSISTING AGENCIES.
POMONA P.D. FOR TRAFFIC CONTROL

SEE FORM 220 GRAND I.C. INC. #251216 FOR ADDT. INFO.

Personnel on Unit LF185

Unit Member 242707 ROY JAMES E
HazMat Exposure Yes
Unit Member 464161 BOYCE WILLIAM M
HazMat Exposure Yes
Unit Member 498097 HATANAKA KYLE M
HazMat Exposure Yes
Unit Member 535606 GUTIERREZ MARIO J

HazMat Exposure	Yes
Unit Member	542948 DARNEY JEFFREY
HazMat Exposure	Yes
Unit Member	613221 HELLEBRAND MATTHEW T
Unit Member	619516 CORMACK JOSEPH D
HazMat Exposure	Yes

Unit E183

Main Use	3 - Other
Unit Type	11 - Engine
Number of Personnel	3
Actions Taken 1	21 - Search
Actions Taken 2	10 - Fire, other
Dispatch Time	08/19/2018 05:57:38
Enroute Time	08/19/2018 05:58:42
Arrival Time	08/19/2018 06:03:56
Clear Time	08/19/2018 09:05:36
Reporting Member	272080 LONG PATRICK T
Assignment Date	08/19/2018

Narrative	<p>Unit Narrative</p> <p>At 0557 hours on Sunday, August 19, 2018 Unit E183. Three personnel responded. We arrived on scene at 0603 hours. The primary task(s) performed at the scene by responding personnel was searching. Assigned to EAST exposure. After exposure secured, assigned RIC until E121 assigned RIC. Then assigned secondary search and then overhaul. FFS Frescas assisted 182/188 with water supply and incident support. No injuries reported.</p>
-----------	--

Personnel on Unit E183

Unit Member	270723 FRESCAS BILL E
Action Taken	11 - Extinguish
Action Taken	12 - Salvage & overhaul
Action Taken	21 - Search
HazMat Exposure	Yes
Unit Member	272080 LONG PATRICK T
Action Taken	11 - Extinguish
Action Taken	12 - Salvage & overhaul
Action Taken	21 - Search
HazMat Exposure	Yes
Unit Member	626283 THIES DANIEL D

Action Taken	11 - Extinguish
Action Taken	12 - Salvage & overhaul
Action Taken	21 - Search
HazMat Exposure	Yes
Communicable Disease	Yes

Unit E182

Main Use	3 - Other
Unit Type	11 - Engine
Number of Personnel	3
Dispatch Time	08/19/2018 05:57:38
Enroute Time	08/19/2018 05:57:45
Arrival Time	08/19/2018 06:04:53
Clear Time	08/19/2018 08:28:05
Reporting Member	None No Report Required
Assignment Date	08/19/2018

Personnel on Unit E182

Unit Member	410588 BOWIE STEVE A
Unit Member	533526 FRYE JEREMY D
Unit Member	541864 TORREZ ELMER G

Unit E188

Main Use	3 - Other
Unit Type	11 - Engine
Number of Personnel	4
Dispatch Time	08/19/2018 05:57:38
Enroute Time	08/19/2018 05:58:20
Arrival Time	08/19/2018 06:03:49
Clear Time	08/19/2018 08:08:43
Reporting Member	None No Report Required
Assignment Date	08/19/2018

Personnel on Unit E188

Unit Member	296772 STYLE RYDELL NEMAR L
Unit Member	428127 GONZALES MARIO L
HazMat Exposure	Yes
Unit Member	442925 FLORES SAM R
HazMat Exposure	Yes
Unit Member	636977 ALVARADO ARIANA M

HazMat Exposure Yes

Unit E184

Main Use 3 - Other

Unit Type 11 - Engine

Dispatch Time 08/19/2018 05:57:38

Enroute Time 08/19/2018 05:58:33

Arrival Time 08/19/2018 06:05:22

Clear Time 08/19/2018 08:12:29

Reporting Member 416516 LOCKETT ROBERT W

Assignment Date 08/19/2018

Narrative E184 was a assigned search and rescue. E184 crew pulled a reel line and follwed fire attack through front of structure and completed a primary search of entire structure with no victims found.

Personnel on Unit E184

Unit Member 416516 LOCKETT ROBERT W

HazMat Exposure Yes

Unit Member 497836 GUZMAN JR. MICHAEL J

HazMat Exposure Yes

Unit Member 645224 WOMMACK JUSTIN H

HazMat Exposure Yes

Unit S183

Main Use 3 - Other

Unit Type 76 - ALS unit

Number of Personnel 3

Actions Taken 1 21 - Search

Actions Taken 2 33 - Provide advanced life support (ALS)

Dispatch Time 08/19/2018 05:57:38

Enroute Time 08/19/2018 05:58:25

Arrival Time 08/19/2018 06:03:39

Enroute Facility Time 08/19/2018 06:24:42

Arrived Facility Time 08/19/2018 06:28:13

Clear Time 08/19/2018 06:38:10

Reporting Member 272080 LONG PATRICK T

Assignment Date 08/19/2018

Narrative Unit Narrative
At 0557 hours on Sunday, August 19, 2018 Unit S183. Three personnel responded. We arrived on scene at 0603 hours and cleared at 0638 hours. The primary task(s) performed at the scene by responding personnel was

searching.

Personnel on Unit S183

Unit Member	450516 CRYDER JOHN T JR
Action Taken	21 - Search
Action Taken	33 - Provide advanced life support (ALS)
HazMat Exposure	Yes
Unit Member	533533 MCNAMARA ERIC P
Action Taken	21 - Search
Action Taken	33 - Provide advanced life support (ALS)
HazMat Exposure	Yes
Unit Member	619513 CARNES ANDREW R
Action Taken	21 - Search
Action Taken	33 - Provide advanced life support (ALS)
HazMat Exposure	Yes
Communicable Disease	No

Unit BC19

Main Use	3 - Other
Unit Type	91 - Mobile command post
Number of Personnel	1
Dispatch Time	08/19/2018 05:57:38
Enroute Time	08/19/2018 05:58:21
Arrival Time	08/19/2018 06:08:44
Clear Time	08/19/2018 07:24:08
Reporting Member	None No Report Required
Assignment Date	08/19/2018

Personnel on Unit BC19

Unit Member	451294 SVOBODA THEODORE M
-------------	---------------------------

Unit S184

Main Use	3 - Other
Unit Type	76 - ALS unit
Number of Personnel	2
Dispatch Time	08/19/2018 06:07:23
Enroute Time	08/19/2018 06:08:51
Arrival Time	08/19/2018 06:19:00
Clear Time	08/19/2018 07:03:13

Reporting Member None No Report Required

Assignment Date 08/19/2018

Personnel on Unit S184

Unit Member 459014 CARVALHO JOE C

Unit Member 499144 MINER JOHN D

Unit E121

Main Use 3 - Other

Unit Type 11 - Engine

Number of Personnel 3

Dispatch Time 08/19/2018 06:08:36

Enroute Time 08/19/2018 06:08:45

Arrival Time 08/19/2018 06:50:58

Clear Time 08/19/2018 06:50:58

Reporting Member None No Report Required

Assignment Date 08/19/2018

Personnel on Unit E121

Unit Member 283683 WASHINGTON KENNETH L

HazMat Exposure Yes

Unit Member 489684 DAVIS GREGORY G

HazMat Exposure Yes

Unit Member 636972 MATYAS DAVID J

HazMat Exposure Yes

Unit INV1

Main Use 3 - Other

Unit Type 00 - Other apparatus/resource

Number of Personnel 0

Dispatch Time 08/19/2018 08:19:56

Enroute Time 08/19/2018 08:25:56

Arrival Time 08/19/2018 08:50:09

Clear Time 08/19/2018 10:26:20

Reporting Member None No Report Required

Assignment Date 08/19/2018

Unit INV3

Main Use 3 - Other

Unit Type 00 - Other apparatus/resource

Number of Personnel 0

Dispatch Time	08/19/2018 08:19:56
Enroute Time	08/19/2018 08:25:56
Arrival Time	08/19/2018 08:50:09
Clear Time	08/19/2018 10:26:20
Reporting Member	None No Report Required
Assignment Date	08/19/2018

Unit INV9

Main Use	3 - Other
Unit Type	00 - Other apparatus/resource
Number of Personnel	0
Dispatch Time	08/19/2018 08:19:56
Enroute Time	08/19/2018 08:25:56
Arrival Time	08/19/2018 08:50:09
Clear Time	08/19/2018 10:26:20
Reporting Member	None No Report Required
Assignment Date	08/19/2018

Fire: 2018-0251216-000**Property & Ignition**

Number of Units	1
Cause of Ignition	5 - Cause under investigation
Area of Origin	UU - Undetermined
Heat Source	UU - Undetermined

Equipment Involved in Ignition

Portability	1 - Portable
Power	11 - Electrical line voltage (> 50 volts)

Building: 2018-0251216-000**Description & Damage**

Structure Type	1 - Enclosed building
Building Status	2 - Occupied and operating
Fire Spread	5 - Beyond building of origin
Story of Fire Origin	1
Square Footage of Main Floor	1200

Detectors

Detectors Present	No
-------------------	----

Automatic Extinguishment System

System Present No

Building Information

Roof Covering 2 - Composition Shingles